Mammo Coach Information and Non Routine Repairs

License Plate Number PIU 4689

VIN 4S7HT9J0XTC018133

Vehicle Yr/Mk/Wt 1996, Spartan, Gross Wt 29410

Cummins diesel Milage 199,100

Kubota 20kw generator 4466 hours

Coach has had routine engine and generator oil and filter changes. There are additional repairs that have been carried out on various issues related to wiring, bulbs, fan, batteries, nuts-bolts and such. I have tried to highlight the bigger items.

1/28/01	Changed transmission filter/ fluid
11/10/20	Roof re-sealed. Heat blaster motor replaced
10/13/20	new front and rear leveling valves, new coolant hose, new belt installed,
	New shocks, new u-joint on steering knuckles
6/22/20	new axle gasket
03/23/20	Bridgestone R268 265/75R22.5 14 ply ALL four rear tires (196550 mi)
03/03/20	Front tires 265/75R22.5 14G (196500 mi)
1/21/20	Replaced blower motor, new thermostat
5/13/19	Repaired HVAC box
3/7/19	New starter
06/21/18	replaced injection pump
05/25/18	replaced relays
04/09/18	replaced radiator hoses
2/27/18	new windshield wiper mounts, motor, arms and r/l spray fittings

08/15/17	New tires Bridgestone or Goodyear, four tires, at 155000 mi
04/17/17	Installed new step motor assembly
03/06/17	Wiper motor
02/15/17	Replaced door lock
12/09/16	new wiper motor installed
10/31/16	Repaired windshield wiper mechanism
08/05/16	Replaced rear brake drums / new leveler
03/28/16	Installed new throttle lever and ball joints / hydraulic hoses
10/20/15	replaced AC condenser
06/19/15	Repaired hydraulic leveler
06/05/15	Installed guard for generator
04/28/15	AC compressor, Motor rebuilt, head gasket, new heater box and heater hoses
02/16/15	Replaced external vacuum pump, rewired for heater

11/21/14 Stabilizer jacks